

Norman H. Bangerter Governor Dee C. Hansen Executive Director Dianne R. Nielson, Ph.D. Division Director

### State of Utah

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

April 17, 1992

Mark Lindsey, Secretary Native Asphalt Company 136 E. South Temple Salt Lake City, UT 84111

Dear Mr. Lindsey:

Re: Water Quality Degradation (March 16, 1992 Response), Native Asphalt Company, Cameron #1, S/047/036, Uintah County, Utah

The details of your proposed action to mitigate the water degradation situation at the mine site, as described in your "fax" letter of March 16, 1992, are unclear. The Division has several questions regarding the proposal which you will need to respond to. What impacts will removal ("cleaning") the present dam area have on the "riparian area" at the dam? What are the rational/calculations and assumptions made in the selection of the culvert and diversion ditch sizes? What are the drainage area parameters and design storm/discharge (cfs) parameters? Will water be impounding behind the floodgate?

Please provide a schematic of the proposal with detail sections of the "cleaned" dam area, the lined diversion ditch, the floodgate to corrugated pipe transition, the floodgate (?) to PVC pipe transition and the PVC pipe discharge. Please provide an additional drawing of the proposed project which includes the entire proposal, surface contours, and mine operations.

After this information has been received by the Division, we will be able to evaluate your proposal. The Division is also interested in the status of the planned staking and land survey which was to be coordinated by April 1, 1992. Please provide information regarding the outcome of this survey.

Thank you for your cooperation in resolution of this matter. If you have any questions in this regard please contact me.

Sincerely,

Chilliany a. Gallege Anthony A. Gallegos

jb

Kathy Trott, Army Corps of Engineers

5/047/036

TELECOPIER COVER LETTER
THE NATIVE ASPHALT COMPANY
1750 UNIVERSITY CLUB BUILDING
SALT LAKE CITY, UTAH 84111

DATE: 8-16-92		
PLEASE DELIVER THE FOLLOWING PAGES TO:		
NAME: Wayne Halbera		
LOCATION: 066M		
FROM: M. Lindson		
TOTAL NUMBER OF PAGES 4 INCLUDING COVER SHEET		
IF YOU DO NOT RECEIVE ALL THE PAGES, PLEASE CALL BACK	AS SOON	AS
POSSIBLE, GAY ROKICH AT 801-532-7510		
TRANSMITTING FROM: 801-532-7519		
TELECOPIER OPERATOR:		
IESSAGE:		
Till Goud hard capies		

in the mail

Mark

AR-16-92 MON 12:22 Arentz Engineers

### THE NATIVE ASPHALT COMPANY

136 East South Temple University Club Building, Suite 1750 Salt Lake City, Utah 84111 (801) 532-7510

3-16-92

D. Wayne Hedberg Division of Oil Gas and Mining 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203

RE: Water Quality Degradation/Diversion Ditch

, wever this?

### Dear Wayne:

The issue of runoff water flowing over the mine area is an issue we have spent much time trying to resolve. The construction of the dam and water system was successful initially but long term the system failed and compounded our problems. We believe that a skimming and ponding effort doesn't solve our long term problem of water in the mine area.

I have been in contact with Aztec Pipe in Vernal and Amcor in Salt Lake and with their help developed a plan that should insure success of a water delivery system and eliminate concern of water in the mine and water quality degradation.

We propose that the present dam area be cleaned and a diversion ditch be channeled. The diversion ditch would cover approximately 10 X 5 feet and would be lined with clay and cobble sized rock (rip-rap). At the end of the ditch a corrugated steel floodgate would be installed to capture water from the ditch flowing through a 10 inch corrugated pipe attached to the floodgate and then into a 6 inch PVC pipe that would extend above ground for a distance of approximately 400 feet. The water runoff would then discharge into the natural drainage below the mine area.

This plan would eliminate any dams and would carry water past the mine site without water quality degradation. We would enact this plan prior to any additional mining on the property.

I am enclosing diagrams of the floodgate proposed for use. Should you have any question regarding this plan, then phone me or Sam Arentz at the above phone number.

Sincerely

Mark F. Lindsey Secretary

04

# Section II— CSP COUPLING SYSTEMS

### Corrugated Steel Pipe Field Joints for


The functional requirements for pipe joints are specified in the AASHTO Bridge Design Specification, Section 2.23.). The design of field joints using these criteria is covered in Chapter 6.

rugated steel pipe. The fellowing drawings illustrate and beline the standard A wide variety of pipe joints are available for field cornecting lengths of cor-

joints which are tabulated in Table 1-10.

CSP FIELD JOINTS

Tipe-Hand Coupling



- I. The rared common CSP Joint users a band mound the pipe joint. 2. The band is thannoud secured on the gipe to connecting devices.
- 3. The pipe ends may be identical to the rest of the pipe board iplain end it, or In the case of helical pipe, the pipe ends al joints may be reformed to an

namular ressurance to flange (reference ends).

4 Gaskels of three lppes are used apporting to bent types; o-ting, sleeve

9
7*
-
-


2	0	*	Ø	<b>5</b> □			1	=
143	paner.)	H-TZR	Company	latives sa*	Reff Liselian			Table 1-10
T	3	1	~~~	4				
×	بر	u	Х	^	Saku			
м	р ж		Ų	×	Shap	E Shape		
*		M	~	×	,	7		
~		14	,		1			
*			75	A	2 ×		Sarkels	•
~	_		~	н	I			
,		24	. ,,,	•	7	H PONT		i
,	i		×	, ж	2.5		Pice Ind	!
- >	< >	. >	, >	( ж	Falors	F.ka		1
							ŧ	

; ;

Fight Type

Wing Chemiel Type

## FIELD JOENTS



## Standard CSP Band Types

